# **Temperature sensor** Clamp-on

Dimension range	PN	Temperature range	Material
4-57 mm	-	-40°C to +150°C	Stainless steel /Plastic

## **Range of application**

For measuring the surface temperature of pipes and control of processes. Used eg Of the life and pharmaceutical industry where there are greater hygiene requirements.

# UBB.32 Temperature transmitter

Continuous output signal 4-20 alt. Pt100 signal.

## **Quality assurance**

Class A acc. to EN60751. Transmitter acc. to directive EMC 2004/107/EC.

## **Material Specification**

1	Insulating material	Plastic		
2	Heat transfer plate	Stailess steel 1.4305	1	1
3	Neck	Stailess steel 1.4305		

## Measurement

A	83,5
В	51
С	60





# **Function and design**

Temperature sensors primarily intended for hygiene applications where interference in the pipes is not desirable. Easily mounted on existing pipes. No welding required. The heat transfer between the PT100 sensor and the tube is achieved through a built-in contact system (a stainless steel ink). The PT100 sensor is protected by an insulating, removable block of heat-resistant plastic. Measurement technology PT 100, wire. Measurement range -40 ° C to + 150 ° C. Output PT 100 alternatively 4-20mA. The extremely small delay this method causes, compared to a traditional solution is usually negligible. See diagram.



rör-Ø	Α	В	С
4-17.2	20	30	35
18-38	30	40	70
38.1-57	40	50	85

# **Temperature sensor** Clamp-on



### **Technial information**

PT100 sensor	
Measuring range	-40°C to +150°C
Connection	3-wire
Accuracy PT100 element	Class A acc. to EN 60751
Protection class	IP65
Pipe dimension	457mm (outside diameter)
Electrical connection	Cable entry
Alternative oouput signal (stated upon ordering)	4-20mA

### **Technical information**

Transmitter (option)		
Supply voltage	24VDC	
Connection	2-wire	
Working temperature	-40°C to +85°C	
Output signal*	4-20mA, invertable	
Response-time*	1s (standard)	
Accuracy (RTD)	$\leq \pm 0.3 \ ^{\circ}\text{C}$	
*Wanted inverted signal or other respons time, specify this when ordering.		

#### Accessories and options

As an option, the temperature sensor can be ordered with output 4-20mA. Measurement area is stated when ordering. Desired software for transmitter programming "Loop Link 5905" can be ordered separately..

## Installation

The insulating plastic block consists of two parts and is mounted outside the tube by means of two hexagonal screws. It is important that the heat transfer plate is positioned against the pipe for best measurement results. The PT100 sensor can be mounted in any position but is advantageously fitted with the PT100 sensor underneath the tube, especially with steam or liquids.

### How to order

Example: AT 7780-33,7T				
AT 7780	33,7	Т		
Fig.no.	The pipes outer diameter	Transmitter		



red

6 2

white

1

